

Lee's Auto Body & Paint

7958 Cameron Brown Court

Springfield, VA 22153

Phone #: (703) 455-5525

Fax #: (703) 455-5113

E-Mail: manager@LeesAB.com

Customer No: 1096

Report No: 1027

Claim #:

Assign No:

Estimate

5/1/2008

Vehicle Information	Owner - James E Norieja	Accident Location
1972 Volkswagen Beetle	Springfield, VA 22153	
Style:	Home Phone: [REDACTED]	
Color:	Work Phone: (703) -	Phone #1: -
Color Code:	Fax #: (703) -	Phone #2: -
Production Date: / 0	Insured -	Claimant -
License: State: VA		
VIN:		
Miles In: 0	Home Phone: (703) -	Home Phone: (703) -
Miles Out: 0	Work Phone: (703) -	Work Phone: (703) -
Condition:	Fax #: (703) -	Fax #: (703) -
Estimator: Young/Chang/Tim	Date of Loss: 4/7/2008	Date of Inspection: 4/7/2008
Date Assigned: 4/7/2008		

Description of Work	Part Number	Price	Labor	Paint	Other
* Repair body work +Clearcoat (20.0*)			80.0* body*	40.0*	
* R&I F+r bumpers.mouldings and all trims. * undercoating inc			10.0* body*	20.0	
Sub Totals			90.0	55.0	

IN BUSINESS SINCE '89
HIDDEN DAMAGE POSSIBLE

THANK YOU FOR LETTING US SERVE YOU

	Hours	Rate	Total
Body Labor	90.0hrs	[REDACTED]	[REDACTED]
Paint Labor	40.0hrs	[REDACTED]	[REDACTED]
Clearcoat Labor cap@15.0hrs		[REDACTED]	[REDACTED]
Paint Supplies	40.0hrs	[REDACTED]	[REDACTED]
Clearcoat	20.0hrs	[REDACTED]	[REDACTED]
Tax		[REDACTED]	[REDACTED]
Grand Total		[REDACTED]	[REDACTED]

5/1/08 Deposit

[REDACTED]

Balance

[REDACTED]

Estimate based on MOTOR CRASH ESTIMATING GUIDE. Unless otherwise noted all items are derived from the Guide. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Guide used is (EOA9103). 2/08

* Indicates Estimator's Judgment
† Indicates Taxed Item